

LinHES - Bug # 515: firmware missing for HVR-1600 card

Status:	Closed	Priority:	Normal
Author:	lucidblue	Category:	
Created:	08/19/2009	Assignee:	cecil
Updated:	03/20/2010	Due date:	12/31/1969
Description:	<p>In the default install the cx18 driver seems to load but it complains that it cannot find the firmware. After copying the 3 firmware files into /lib/firmware everything worked fine and seems to work correctly.</p> <p>the 3 files:</p> <p>v4l-cx23418-apu.fw v4l-cx23418-cpu.fw v4l-cx23418-dig.fw</p> <p>Link to download for downloading: http://dl.ivtvdriver.org/ivtv/firmware/cx18-firmware.tar.gz</p> <p>Info found at: http://www.mythtv.org/wiki/Hauppage_HVR-1600</p> <p>Thanks, LB</p>		

History
